


CA2 ON
EV.660
2007
S21
c.2

January 2007

Sediment Chemical Assessment of the Cornwall Canal, St. Lawrence River, Ontario



Protecting our environment.



Ontario

Copyright Provisions and Restrictions on Copying:

This Ontario Ministry of the Environment work is protected by Crown copyright (unless otherwise indicated), which is held by the Queen's Printer for Ontario. It may be reproduced for non-commercial purposes if credit is given and Crown copyright is acknowledged.

It may not be reproduced, in all or in part, for any commercial purpose except under a licence from the Queen's Printer for Ontario.

For information on reproducing Government of Ontario works, please contact ServiceOntario Publications at copyright@ontario.ca

**Sediment Chemical Assessment of the Cornwall Canal,
St. Lawrence River, Ontario**

**Report Prepared by:
Lisa A. Richman
Water Monitoring and Reporting Section
Environmental Monitoring and Reporting Branch
Ontario Ministry of the Environment**

Cette publication technique
n'est disponible qu'en anglais



Printed on recycled paper

Copyright © Queen's Printer for Ontario, 2007
This publication may be reproduced for non-commercial
purposes with appropriate attribution.

ISBN 978-1-4249-3054-8

PIBS 6036e

FOREWORD

Since 1970 there have been several sediment surveys in the St. Lawrence River along the Cornwall waterfront to delineate the extent of sediment contamination and to associate these contaminants with local point sources. These surveys identified mercury contaminated sediment extending downstream from Domtar Fine Paper Ltd. and ICI Forest Products (formerly called CIL), and adjacent to, and downstream of the former Courtaulds Fibres Canada property (Richman and Dreier 2001).

Work undertaken as part of the Cornwall Sediment Strategy (sampling of perch from along the Cornwall waterfront and methyl-mercury modeling), suggested the potential existence of a fugitive source(s) of methyl-mercury. As a follow-up to this issue, a project titled "Cornwall Mercury Trackdown", was initiated to determine whether a fugitive source of mercury exists and to identify and take appropriate abatement action if required. Accordingly, this project was put forward to determine whether the Cornwall Canal is a source of mercury to the Cornwall waterfront. The data from this report will be integrated with additional information generated by related studies in the St. Lawrence River to track down potential local sources of mercury.

This report has been prepared under the auspices of the Canada-Ontario Great Lakes Remedial Action Plan Program. Financial support for the sampling projects, data analysis and report writing was provided by the Ontario Ministry of Environment (MOE) and Environment Canada. The track-down of Hg sources to the Cornwall waterfront is a multi-agency project coordinated by MOE's Eastern Region, with involvement from the City of Cornwall, The Raisin River Conservation Authority, Environment Canada, St Lawrence River Institute of Environmental Sciences (SLRIES) and MOE (Environmental Monitoring and Reporting Branch).

For additional technical reports or information on the St. Lawrence River Remedial Action Plan (RAP), contact the Ontario Ministry of Environment at 133 Dalton Road, Kingston Ontario, K7L 4X6.

ACKNOWLEDGMENTS

The author would like to acknowledge the assistance and time commitment of Duncan Boyd and Conrad Debarros of the Ministry of Environment (MOE) for their review of the report.

The author would like to acknowledge John Kraft from EC for providing equipment and a survey vessel and John Thibeau for assistance with the sample collection.

Laboratory sample analyses were performed by MOE Laboratory Services Branch. A subset of sediment samples were submitted to Flett Research Ltd. Laboratory in Winnipeg, Manitoba for methyl and total mercury analysis.

This study was funded in part by EC and MOE under the terms of the Canada-Ontario Agreement respecting Great Lakes Basin Ecosystems.

SUMMARY

The St. Lawrence River near Cornwall, Ontario was designated as a Great Lakes Area of Concern (AOC) in 1985 by the International Joint Commission in part because of contaminated sediment located along the north shore of the Cornwall waterfront. Sediment surveys along the waterfront since 1970 showed sediment concentrations greater than the "severe effect level" (SEL) of the Ontario Sediment Quality Guidelines for mercury extending downstream from Domtar Fine Paper Ltd. (herein referred to as Domtar) and ICI Forest Products (formerly called CIL). Sediment downstream of the former Courtaulds Fibres Canada facility (herein referred to as Courtaulds) had concentrations greater than the SEL for mercury, lead, copper and zinc (Richman and Dreier 2001). As such, a Remedial Action Plan (RAP) to improve the local conditions of the aquatic environment identified the need to address the issue of sediment contamination along the Cornwall waterfront (Dreier *et al.* 1997).

Work undertaken as part of the Cornwall Sediment Strategy (sampling of perch from along the Cornwall waterfront and methyl-mercury modelling), suggested the potential existence of a fugitive source(s) of methyl-mercury. As a follow-up to this issue, a project titled "Cornwall Mercury Trackdown" was initiated to determine whether a source of mercury exists and to identify and take appropriate abatement action if required. To support this project the MOE Environmental Monitoring and Reporting Branch collected sediment from the Cornwall Canal. To date, there was relatively little information on the sediment quality of the canal.

The objectives of the 2004 sediment survey were as follows:

- (1) *assess total and methyl mercury concentrations in sediment and determine whether the canal was a significant source of mercury to the Cornwall waterfront.*
- (2) *determine if concentrations of various metals and trace organics in sediment located in the canal exceed the Provincial Sediment Quality Guidelines "severe effect level" (SEL) and "lowest effect level" (LEL).*

Surface sediment (top 3 cm) was collected from 18 stations (arranged along 7 transects) using a stainless steel mini ponar (Figure 1). At one station along each transect a core sample was collected (using a hand-held benthos-sized corer). Sediment samples were analysed for trace metals including methyl mercury, organochlorinated pesticides, total PCBs (polychlorinated biphenyls), PAHs (polycyclic aromatic hydrocarbons), % TOC (total organic carbon) and particle size.

CONCLUSIONS

With the exception of one station, the data on methyl and total mercury (Hg) in sediment suggested that the canal sediments are not highly contaminated and are, therefore, not likely to be a significant source of Hg to the St. Lawrence River, particularly when

compared to sediment data collected from sites downstream of historical discharges. Total mercury concentrations in surface sediment were low and typically below the LEL (0.2 ug/g) at most stations. Higher concentrations of total and methyl Hg were present in sediment collected from the lower segment of the canal when compared with the upper segment, and the data suggested some Hg enrichment relative to local background condition. However, concentrations of total Hg were all less than the SEL. At one station in the lower segment of the canal methyl Hg was low in the surface sample and similar in concentration to other samples in the survey, but the more elevated concentrations within the core suggested increased mercury methylation with sediment depth. This station, located just downstream of an outfall which may have been associated with Domtar, also had sediment concentrations of nickel (Ni), copper (Cu) and iron (Fe) that were greater than the SEL within the deeper core segments and the highest concentration of total PCBs compared with other stations in the survey.

In general, throughout the canal, sediment concentrations of TOC and metals (with the exception of Transect 1 and manganese), were above the LEL. Cu, Fe and Ni concentrations were greater than the SEL in only one core sample (described above). In general, concentrations of Cu, Hg and Ni tended to be higher in the lower segment of the canal when compared with the upper segment of the canal. Pb, Cu and Zn concentrations were higher at several stations throughout the canal than concentrations along the Cornwall waterfront that were considered to represent local background conditions. Nevertheless, these values were well below the SEL and likely not problematic for biota living in or on the sediment.

TOC concentrations in more than half the sediment samples collected at, and downstream of, Transect 3, were greater than the SEL (100 mg/g) which indicated highly organic sediment. The highest concentration (470 mg/g) was present at Transect 4 which was located immediately downstream of an outfall that has been identified as a storm sewer which collects runoff from the surrounding area (L. Chalmers, personal communication).

Total PCBs were present in almost all sediment samples at concentrations greater than the LEL (0.07 ug/g). The maximum concentration was 550 ng/g present in sediment from the lower segment of the canal. Concentrations of total PAHs in sediment were typically greater than the LEL (4 ug/g) at most stations. The SEL was not exceeded in any samples for PAHs. The highest concentrations were present in the surface samples (top 3 cm) compared with the core samples which suggested an increase in recent PAH contamination.

TABLE OF CONTENTS

LIST OF FIGURES	vi
LIST OF APPENDICES	vii
INTRODUCTION	1
METHODOLOGY	2
Sampling Stations and Field Methods	2
Sediment Collection for Contaminant Analysis	2
Sample Submission for Contaminant Analysis	5
Data Analysis	5
Identification of Contaminated Sediment	5
Particle Size Correction Method	5
RESULTS AND DISCUSSION	6
Patterns of Sediment Contamination	6
Mercury and Methyl Mercury	6
Metals	11
Total PCBs, Organochlorinated Pesticides and Chlorinated Benzenes	13
Polycyclic Aromatic Hydrocarbons (<i>PAHs</i>)	13
CONCLUSIONS	15
REFERENCES	16
APPENDIX	18

LIST OF FIGURES

Figure 1: Study area and transect locations	3
Figure 2: Study area and sampling sites	4
Figure 3: Total mercury concentrations ($\mu\text{g/g}$) in surface sediment (top 3 cm) (MOE Laboratory)	7
Figure 4: Total and methyl mercury concentrations (ng/g) in surface and core segments (Flett Laboratory)	9
Figure 5: Sediment methyl Hg concentrations vs total Hg concentrations	10
Figure 6: Total Organic Carbon concentrations (mg/g) in surface sediment (top 3 cm)	12
Figure 7: Metal concentrations ($\mu\text{g/g}$) in surface sediment and core segments at Transect 4&6	14

LIST OF APPENDICES

Table A1: Metals, LOI and TOC concentrations in sediment samples collected from the Cornwall Canal, 2004

Table A2: Organochlorinated pesticides and chlorinated benzenes (ng/g dry weight), in sediment samples collected from the Cornwall Canal, 2004

Table A3: Polycyclic aromatic hydrocarbons (ng/g dry weight), in sediment samples collected from the Cornwall Canal, 2004

Appendix B: Particle size correction information.

Sediment contaminant data normalized to a fine ($< 63 \mu\text{m}$) particle content of 67%.

Appendix C: Median metal, total phosphorus and TOC concentrations ($\mu\text{g/g}$ dry weight) in sediment samples collected from the St. Lawrence River, along the Cornwall waterfront, 1997.

INTRODUCTION

The St. Lawrence River near Cornwall, Ontario was designated as a Great Lakes Area of Concern (AOC) in 1985 by the International Joint Commission in part because of mercury (Hg) contaminated sediment. As such, a Remedial Action Plan (RAP) to improve the local conditions of the aquatic environment identified the need to address the issue of sediment contamination along the Cornwall waterfront (Dreier *et al.* 1997) and a sediment management plan was developed.

Since 1970 there have been several sediment surveys in the St. Lawrence River along the Cornwall waterfront to delineate the extent of sediment contamination and to associate these contaminants with local point sources. These surveys identified mercury contaminated sediment extending downstream from Domtar Fine Paper Ltd. (herein referred to as Domtar) and ICI Forest Products (formerly called CIL), and adjacent to, and downstream of the former Courtaulds Fibres Canada property (Richman and Dreier 2001). Sediment samples collected in both these areas since 1970 exceeded the "severe effect level" (SEL) of the Ontario Sediment Quality Guidelines for mercury and sediment collected downstream of Courtaulds also exceeded the SEL for lead (Pb), copper (Cu) and zinc (Zn). Work undertaken as part of the Cornwall Sediment Strategy (sampling of perch from along the Cornwall waterfront and methyl-mercury modelling), suggested the potential existence of a fugitive source(s) of methyl-mercury. As a follow-up to this issue, a project titled "Cornwall Mercury Trackdown" was initiated to determine whether a source of mercury exists and to identify and take appropriate abatement action if required. This project was coordinated on behalf of Environment Canada and the Ontario Ministry of Environment by MOE's Eastern Region.

A number of potential sources were sampled and tested for methyl-mercury and trace level total mercury as part of the Cornwall Mercury Trackdown study. These potential sources included: City of Cornwall Storm Sewers – sampling of wet and dry flow events and combined sewer overflow (CSO) events; effluent discharges from Domtar and the City of Cornwall STP - sampled on a quarterly basis; ground water – all monitoring wells located on the properties of ICI and Domtar were sampled; storm water runoff – ICI will be conducting an evaluation of the quality of storm water runoff from their decommissioned property; and soil – soil samples from the snow dump area in Cornwall will be collected from several locations.

To support this project the MOE Environmental Monitoring and Reporting Branch collected sediment from the Cornwall Canal. Historically, there have been industrial and municipal discharges and spills to the canal. Presently, the only outfalls that are known to be active are believed to be storm sewers located along the north side of canal. To date, the chemical characterization of the sediment in the canal was unknown.

The overall objective of the 2004 sediment survey was to characterize the chemical composition of the sediment (surface and at depth) collected from the Cornwall Canal. More specific objectives were to:

- (1) *assess total and methyl Hg concentrations in sediment and determine whether the canal was a significant source of mercury to the Cornwall waterfront.*
- (2) *determine if concentrations of various metals and trace organics in sediment located in the canal exceed the Provincial Sediment Quality Guidelines "severe effect level" (SEL) and "lowest effect level" (LEL).*

Sediment was collected jointly by MOE and Environment Canada (EC) from 18 stations in July, 2004, and samples were analysed for a range of contaminants and physical parameters.

METHODOLOGY

Sampling Stations and Field Methods

Seven transects were identified along the length of the canal beginning at the west end (Figure 1). Typically, three stations were sampled across each transect with the exception of two transects located in the lower part of the canal where only one or two stations were sampled (Figure 2). With only one exception (Transect 6A), a surface sample was collected at all stations along a transect. In addition, one of the three stations was selected for the collection of a core sample. At Transect 6A, only a core sample was collected.

Sediment Collection for Contaminant Analysis

Sediment was collected using a stainless steel mini ponar from 18 stations. A portion of the upper 3 cm of at least 3 grabs (or more if required) were pooled and homogenized for each sample. Sediment was composited in a clean hexane-rinsed glass or ceramic bowl and thoroughly homogenized with a clean hexane-rinsed stainless steel spatula.

Single cores were collected from one station along the transect using a hand-held benthos-sized corer (inside diameter of 67 mm). Cores were sectioned every 10 cm where sufficient material was present. Only the top and bottom 10 cm sections were submitted for analysis. The remaining sections were archived.

All samples were placed in pre-cleaned glass jars with Teflon cap liners and stored in coolers on ice until submission to the laboratory for analysis

Water temperature, DO and conductivity were measured during sediment collection using a handheld system - YSI Model 85, which was calibrated daily.

Figure 1: Location of Transects and Sampling Stations in the Cornwall Canal, 2004





Figure 2: Location of Sampling Stations in the Cornwall Canal, 2004



Sample Submission for Contaminant Analysis

All samples were submitted to the Rexdale Laboratory for analysis. Samples were submitted for trace metals, organochlorinated pesticides, polychlorinated biphenyls (total PCBs), chlorinated benzenes, polycyclic aromatic hydrocarbons (PAHs), percent total organic carbon (% TOC), loss on ignition (LOI) and particle size. Methods for contaminant analysis are provided in MOEE 1989a & b; 2000; 2004.

In addition to the submission of samples to the MOE Rexdale Laboratory, a sub-sample from one surface sample from each transect and a sub-sample from the core samples (top and bottom 10 cm) were submitted to Flett Research Ltd., 440 DeSalaberry Ave, Winnipeg, Manitoba, R2L 0Y7 (204 667-2505) for total and methyl Hg analysis.

Data Analysis

Identification of Contaminated Sediment

Sediment contaminant concentrations were compared with the Provincial Sediment Quality Guidelines (Persaud *et al.* 1992). These guidelines describe three "effect" levels for different contaminants in terms of potential effects on the benthic community: (1) the no observed effect level; (2) the lowest effect level (LEL) which is the level of sediment contamination that can be tolerated by the majority of benthic organisms (concentrations greater than this level indicate that the benthic communities in these areas may be impaired); and (3) the severe effect level (SEL) which is the sediment concentration of a compound that is expected to be detrimental to the majority of benthic species. Sediment contaminant concentrations may exceed the LEL and/or the SEL with no apparent impact on the benthic community, nevertheless these guidelines serve as a point of reference to investigate the extent of sediment contamination within the study area and to compare the relative contamination with other locations.

Particle Size Correction Method

Trace elements tend to accumulate and bind to the clay/silt sediment fraction represented by particle sizes of less than 63 μm (Forstner and Wittmann 1983; Krumgalz *et al.* 1992). Consequently, the heterogenous nature of sediment makes it necessary to adjust trace element concentrations for the different particle size distributions at the various sampling stations in order to compare contaminant concentrations between stations if the effect of depositional environments are to be diminished, and trace metal contaminant sources are to be inferred. There are several methods frequently used to correct for depositional environments and hence particle size differences between stations (Forstner and Wittmann 1983; Krumgalz *et al.* 1992).

The approach taken in this report was to normalize the metal concentrations at all stations to a fine particle (<63 μm) content of 67% (Appendix B). This involved the multiplication of the contaminant concentration at a site by 67% and then dividing by the actual percent silt plus clay for the station. This percentage (67%) was chosen since it was the median value for the particle

size distribution for all samples collected in the study area. Another commonly used option would have been to normalize the concentration of contaminants to a fine particle content of 100% however, this method has a tendency to produce inordinately high metal concentrations at stations high in sand.

RESULTS AND DISCUSSION

Patterns of Sediment Contamination

Data for sediment contaminant concentrations and particle size for stations sampled in the Cornwall Canal were summarized in Tables A1 to A3. These tables are located in the Appendix of this report.

Mercury and Methyl Mercury

Total mercury (Hg) concentrations in surface sediment were low and typically below the LEL at all stations between Transects 1 to 5 (Table A1; Figure 3). A comparison of the data for samples analysed by both the MOE and Flett laboratories showed that concentrations were similar, however, the Flett data were in general, higher than the MOE data (Table A1). With only one exception (Hg greater than the LEL at Transect 5 using Flett data), this difference did not change the patterns of distribution of Hg within the study area. Concentrations were greater than the LEL in the deeper core segments from the station in Transect 4 and 5 and in the lower canal at Transect 6, 6A and 7 using both datasets. Hg concentrations increased with depth in the sediment core samples at some stations. Sediment did not exceed the SEL for total Hg throughout the study area.

With the exception of the core segments collected from Transects 4, 5, 6 and 6A, total Hg concentrations in the surface (top 3 cm) and top 10 cm of sediment were within the range measured for sediment samples collected from sites located upstream of the Moses Saunders Dam in Lake St. Lawrence. These sites were identified as reference stations in a report by Grapentine *et al.* (2003) which compared total and methyl Hg concentrations in sediment collected from areas impacted by local industries in Cornwall known to have historically discharged Hg to the river. This suggests that the sediment in the upper segment of the canal are not enriched with Hg. Sediment in the lower segment of the canal had total Hg concentrations similar to some sites located along the Cornwall waterfront which suggests some Hg enrichment relative to local background concentrations. When the data were compared to an earlier study of the Cornwall waterfront (Richman 1999), sediment concentrations in the lower segment of the canal were higher than concentrations in sediment considered to be un-impacted by local industry but lower than sediment collected downstream of the historical Hg dischargers (Appendix C). Since the highest concentrations in the canal are located near an outfall that appears to be associated with Domtar (Transect 6), this could be a potential source. However, the discharge

Figure 3: Total Mercury (ug/g) in Surface Sediment Collected From the Cornwall Canal, 2004



history of the outfall is presently unknown. Sediment collected from this station also had the highest concentrations of methyl Hg, Ni and Cu (i.e. greater than the SEL), and total PCBs relative to the other stations in the survey.

Methyl Hg concentrations in sediment followed a similar pattern to total Hg in general (the highest concentrations were present in the core segment of Transect 4 and 5 and in the lower canal at Transects 6, 6A and 7) (Figure 4). Methyl Hg concentrations in the surface samples were higher than in the core samples in Transects 1 to 5 while concentrations increased with core depth at Transect 6. The methyl Hg concentration in the bottom of the core collected from Transect 6 was an anomaly at 13 ng/g compared to all the other samples in the study which ranged from (0.2 to 2.3 ng/g) (Table A1; Figure 4). This value was confirmed by Flett Laboratory. However, it is unclear why the methyl Hg concentrations increased relative to the other samples in the survey or even within the core. It could possibly be connected to the higher silt content of that sample (70%) compared with the surface sample and other core segment (53% and 56% respectively), but TOC concentrations were similar throughout the core at that station. Interestingly, this segment of the core had the highest Fe concentrations (> SEL) which would suggest that the inorganic Hg would be more tightly bound and less available for methylation rather than the opposite result.

Sediment methyl and total Hg were positively correlated when the methyl Hg outlier was removed from the analysis ($r^2 = 0.52$) (Figure 5). Inclusion of the sample produced an $r^2 = 0.01$.

With the exception of the core segments collected from Transect 6 and 6A, methyl Hg concentrations in the surface (top 3 cm) and top 10 cm of sediment were within the range measured for sediment samples collected from the reference sites located upstream of the Moses Saunders Dam in Lake St. Lawrence (Grapentine *et al.* 2003). The percent methyl Hg was low in all samples. With the exception of two samples, the data showed that between 0.05 % to 0.53 % of the total Hg was present as methyl Hg. Surface sediment collected from Transect 1 had 2.6 % methyl Hg and the sediment from the bottom of the core from Transect 6 had 3.0 % methyl Hg. These ranges in percent methyl Hg were very typical of the data collected by Grapentine *et al.* (2003) from both exposed and reference sites.

Overall, the methyl and total Hg sediment data suggested that although the lower canal sediment were enriched with Hg relative to local background conditions, they were not highly contaminated and were, therefore, not likely to be a significant source of Hg to the St. Lawrence River, particularly when compared to sediment data collected from sites downstream of historical discharges. The concentration range of both total and methyl Hg in sediment collected from the Cornwall waterfront in past surveys were higher than the concentrations measured in the canal in 2004, with the exception of the methyl Hg data from the core segments at Transect 6 and 6A (Richman and Dreier 2001; Grapentine *et al.* 2003).

Figure 4: Total and Methyl Mercury Concentrations (ng/g dry wt.) in Surface and Core Sediment Samples
(analysed by Flett Laboratory)






Figure 5: Sediment Methyl Mercury Concentrations vs Total Mercury Concentrations (minus core bottom sample (13 ng/g) from stn 528)



Metals

In general, throughout the study area, sediment concentrations of TOC and metals (with the exception of Transect 1 and manganese), were above the LEL (Table A1). Concentrations of metals were particularly low in sediment collected from Transect 1 due to the high sand content, and manganese concentrations in general were low at all stations. Concentrations of Cu, Fe and Ni were only greater than the SEL in the core sample collected from one station in Transect 6 where the highest Hg concentrations were detected (Figure 1). In general, however, concentrations of Cu, Hg and Ni tended to be higher in the lower part of the canal (at Transect 6 and 6A) when compared with the first (upper) segment of the canal. This pattern was confirmed when the data were normalized for particle size differences.

TOC concentrations in almost all sediment samples collected at, and downstream of, Transect 3, were greater than the SEL suggesting highly organic sediment (Figure 6). The highest concentration was in sediment from Transect 4 (station 539; 490 mg/g) located immediately downstream of a storm sewer which receives runoff from the surrounding area (L. Chalmers, personal communication). TOC concentrations decreased with increasing distance downstream from the outfall, as well as along Transect 4 (160 mg/g and 140 mg/g) suggesting the outfall as a possible source of the organic matter. TOC concentrations and LOI were highly correlated ($r^2 = 0.92$). TOC was not correlated with percent silt/clay ($r^2 = 0.07$). However, the correlation improved ($r^2 = 0.39$) with the removal of station 539.

At Transects 1, 2, 3 and 5 only one core segment was available (maximum core length was 12 cm). A comparison of sediment surface chemistry (top 3 cm) with the core sample (0 to 6 cm) at Transect 1 showed no difference in metal concentrations (Table A1). When the data were corrected for particle size differences, concentrations of most metals were higher at the surface compared with the core sample although the increase was not large. At Transect 2 and 3 where core lengths were 0 to 9 cm and 0 to 12 cm respectively, surface samples had higher metal and TOC concentrations than the cores. TOC concentrations were two to three times higher in the surface samples. Correcting the metal concentrations for particle size reduced the differences in concentration between the surface and the core samples although Pb and Zn were still higher at the surface in Transect 3. Concentrations of metals and TOC in the surface sample from Transect 5 were similar to the concentrations in the 0 to 7 cm core with a tendency towards higher concentrations at depth for Fe, Mn and Pb. Particle size corrections did not change the patterns.

Although cores were not dated and deposition rates were unknown, a review of the data overall (with the exception of Transects 4 and 6 discussed below), suggested little change in metal concentrations with time assuming the deeper sediments represent historical conditions.

At Transect 4 (downstream of the storm sewer), the core was sectioned into two segments; 0 to 10 cm and 10 to 19 cm. Sediment chemistry within the two sections were similar for all parameters and were higher than concentrations at the surface (top 3 cm) possibly suggesting historical contamination which may have come from the outfall.

Figure 6: Total Organic Carbon (mg/g) in Surface Sediment Collected From the Cornwall Canal, 2004



(Table A1) (Figure 7). Likewise, Transect 6 (station in the lower canal segment which was in the vicinity of the outfall) had higher concentrations of some metals in the core when compared with the surface sample. In this case the core segment from 0 to 10 cm and from 20 to 31 cm (bottom of the core) were analysed. Ni, Pb and Cu concentrations were highest in the 0 to 10 cm section (> SEL) while iron was highest in the 20 to 31 cm section. Zn was similar at the surface and in the 0 to 10 cm section and was greater than the 20 to 31 cm section. Particle size corrections did not alter the patterns in either Transect 4 or 6.

Sediment concentrations for aluminum, cadmium, chromium, iron and manganese in the canal were similar to concentrations present along the north shore of Cornwall Island, which historically has not been impacted by local industry (Appendix C) (Richman 1999). This suggests that there has been little contaminant enrichment in the canal over time for these metals. In general, Pb, Cu and Zn concentrations in the canal were higher at several stations than concentrations along the north shore of Cornwall Island but well below the SEL and likely not problematic for biota living in or on the sediment. TOC concentrations throughout most of the canal indicated highly organic sediment which could potentially have an effect on the local benthic community.

Total PCBs, Organochlorinated Pesticides and Chlorinated Benzenes



Total PCBs were present in all sediment samples with the exception of Transect 1 (Table A2). The highest concentrations were present in sediment collected from Transect 6 and 6a in the lower part of the canal. The same pattern was present when total PCB concentrations were normalized for TOC concentrations. At Transect 4, 5, and 6, surface samples had higher PCB concentrations than core samples when normalized for TOC. Concentrations increased in sediment from the west to east end of the canal.

In general, with the exception of dieldrin, p,p'-DDE, 1,2,4- and 1,3,5-trichlorobenzene and pentachlorobenzene, trace concentrations of organochlorinated pesticides and chlorinated benzenes were detected only sporadically in sediment samples. Dieldrin was detected at trace concentrations in all samples collected from Transect 4 and in several samples in the lower part of the canal. The DDT metabolite, p,p'-DDE, was detected in sediment collected from all seven transects likely reflecting historical use within the area. The highest concentrations were present in Transects 4, 6 and 6a. Concentrations were similar in the surface and core samples at these three transects and ranged from 10 to 20 ng/g. Core samples collected from Transect 5, and 6 had trace and detectable concentrations of 1,2,4-trichlorobenzene and pentachlorobenzene. The bottom core sample at transect 4 also had detectable concentrations of 1,3,5 - trichlorobenzene (43 ng/g).

Polycyclic Aromatic Hydrocarbons (PAHs)

Concentrations of total PAHs in sediment were typically greater than the LEL (4 ug/g) at most stations with the exception of Transects 1 & 2 where concentrations were less than the LEL

Figure 7: Metal Concentrations (ng/g dry wt.) in Surface Sediment and Core Segments Collected From Transect 4 and 6.



(Table A3). The SEL for PAHs was not exceeded in any samples. The highest concentrations were present in the surface samples (top 3 cm) compared with the top and bottom core samples which suggested an increase in recent PAH contamination. This pattern is consistent even when data were normalized for TOC. The PAH sediment contamination begins at Transect 3. This transect is located downstream of two storm sewers which are the likely source of the high PAHs. The highest PAH concentrations in the survey were present in the surface sample collected from station 525 (151,690 ng/g) which was located on the north side of the canal close to the outfalls.

CONCLUSIONS

The methyl and total Hg sediment data suggested that the canal sediment were not highly contaminated and were, therefore, not likely to be a significant source of Hg to the St. Lawrence River. Total mercury (Hg) concentrations in surface sediment were low and typically below the LEL (0.2 ug/g) in the upper segment of the canal. Sediment in the lower segment of the canal had total Hg concentrations similar to some sites located downstream of historical Hg dischargers along the Cornwall waterfront which suggests some Hg enrichment relative to local background concentrations. However, all Hg concentrations were below the SEL. With the exception of two stations, methyl mercury concentrations in surface and core samples were similar to concentrations previously measured upstream of local industrial sources in Lake St. Lawrence (Grapentine *et al.* 2003). The north station on Transect 6 had the highest total Hg concentrations at the surface and concentrations increased with core depth. Methyl Hg was not high at the surface when compared with the other samples in the survey, but the concentrations within the core suggested increased mercury methylation with sediment depth. This station, located just downstream of an outfall which may have been associated with Domtar, also had high sediment concentrations of Ni, Cu and Fe (i.e. greater than the SEL) and high total PCB concentrations when compared to other stations in the canal.

In general, throughout the canal, sediment concentrations of TOC and metals (with the exception of Transect 1 and manganese), were above the LEL. Cu, Fe and Ni were the only metals found at concentrations greater than the SEL and this only occurred in one core sample collected from one station in Transect 6. In general, concentrations of Cu, Hg and Ni tended to be higher in the lower segment of the canal (at Transect 6 and 6A) when compared with the upper segment of the canal. This pattern was confirmed when the data were normalized for particle size differences. Pb, Cu and Zn concentrations were higher at several stations throughout the canal than concentrations along the Cornwall waterfront that were considered to represent local background conditions. Nevertheless, these values were well below the SEL and likely not problematic for biota living in or on the sediment

TOC concentrations in most sediment samples collected at, and downstream of, Transect 3, were greater than the SEL (100 mg/g) suggesting highly organic sediment which could have the potential to impact the local benthic community.

Total PCBs were present in all sediment samples with the exception of Transect 1.

Concentrations were greater than the LEL (0.07 ug/g) at most stations but did not exceed the SEL. The highest concentrations were present in sediment collected from Transect 6 and 6a in the lower part of the canal (range: 200 ng/g to 550 ng/g).

Concentrations of total PAHs in sediment were typically greater than the LEL (4 ug/g) at most stations. The SEL was not exceeded in any samples. The highest concentrations were present in the surface samples (top 3 cm) compared with the core samples which suggested an increase in recent PAH contamination.

REFERENCES

- Dreier, S.I., Anderson, J., Biberhofer, J., Eckersley, M., Helliard, R., Hickey, M.B.C., Richman, L., Stride, F. and the St. Lawrence River (Cornwall) Remedial Action Plan Public Advisory Committee. 1997. Great Lakes, Great River. Remedial Action Plan for the St. Lawrence River (Cornwall) Area of Concern Stage 2 Report: The Recommended Plan.
- Forstner, U., and Wittmann, G.T.W. 1983. Metal Pollution in the Aquatic Environment. 2nd Revised Ed. Springer-Verlag. Berlin Heidelberg New York Tokyo.1983.
- Grapentine, L., Milani, D., and Mackay, S. 2003. A study of the bioavailability of mercury and the potential for biomagnification from sediment in the St. Lawrence (Cornwall) area of concern. Environment Canada (Draft report).
- Krumgalz, B.S., Fainshtein, G. and Cohen, A. 1992. Grain size effect on anthropogenic trace metal and organic matter distribution in marine sediments. *Sci. of Tot. Env.* **116**: 15-30.
- Ontario Ministry of the Environment (MOE) 1983. Handbook of Analytical Methods for Environmental Samples. Laboratory Services and Applied Research Branch. Toronto, Ontario.
- Ontario Ministry of the Environment (MOE) 1989a. The determination of trace metals in sediments by the spectro inductively coupled plasma-optical emission spectrometer (ICP-OES). Laboratory Services Branch, Etobicoke, Ontario.
- Ontario Ministry of the Environment (MOE) 1989b. The determination of mercury in soils, sediments and vegetation by cold vapour-atomic absorption spectrophotometry (CV-AAS). Laboratory Services Branch. Etobicoke, Ontario.
- Ontario Ministry of Environment and Energy (MOEE), 2000. The Determination of total carbon in sediments by the LECO carbon analyzer. CARBONTC-E3142A. December 4, 2000. Laboratory Services Branch, Etobicoke, Ontario.
- Ontario Ministry of Environment (OMOEE), 2004. The Determination of Particle Size

Distribution on Sediments Particulate Matter and Liquids by Coulter Model LS230 Particle Size Analyzer, LLPART-E3328A, 2004. Laboratory Services Branch, Quality Management Office. Etobicoke, Ontario.

Persaud, D., Jaagumagi, R., and Hayton, A. 1992. Guidelines for the protection and management of aquatic sediment quality in Ontario. Water Resources Branch. Ontario Ministry of the Environment. Toronto, Ontario.

Richman, L.A. 1996. St. Lawrence River sediment assessment, 1994, Cornwall, Ontario. St. Lawrence RAP Technical Report No. 7.

Richman, L.A. 1999. St. Lawrence River sediment chemical assessment 1997, Cornwall, Ontario Ontario Ministry of Environment ISBN 0-7778-9064-X.

Richman, L. A. and Dreier, S. I. 2001. Sediment contamination in the St. Lawrence River along the Cornwall, Ontario waterfront. J. Great Lakes Res. 27(1):60-83.

APPENDIX

TABLE A1: Concentration of metals and particle size data for sediment collected from the Cornwall Canal, 2004.

All data represent surface samples (0-3 cm) unless noted as a core sample.

Values > LEL are in bold.

Values > SEL are designated **

Transect #	Station Description	Station	Core Length	Field Sample	Water Depth (m)	Aluminum UG/G DRY	Cadmium UG/G DRY	Chromium UG/G DRY	Copper UG/G DRY
1	West end of Canal								
	North side of canal	1200020533		GL045601	4.2	4900	0.5 <T	12	7
	Center of Canal	1200020534		GL045603	3.3	5600	0.9 <T	16	11
	South side of canal	1200020523		GL045602	3	4800	0.5 <T	13	9
	South side of canal (core top)	1200020523	0 to 6 cm	GL045625	3	5800	0.3 <T	14	9
2	Downstream of Lock (200m)								
	North side of canal	1200020524		GL045605	4.1	14000	1.3	42	55
	North side of canal (core top)	1200020524	0 to 9 cm	GL045627	4.1	7700	0.9 <T	22	21
	Center of canal	1200020535		GL045604	5.5	17000	1.9	50	56
	South side of canal	1200020536		GL045606	5.9	18000	2.1	53	61
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		GL045608	4	13000	1.9	39	62
	North side of canal (core top)	1200020525	0 to 12 cm	GL045629	4	8300	0.9 <T	24	34
	Center of Canal	1200020537		GL045607	5.1	11000	1	31	40
	South side of canal	1200020538		GL045609	2.6	11000	1.5	33	53
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		GL045611	3.2	6900	1	17	35
	Center of canal	1200020526		GL045610	4.6	8500	1.2	22	32
	Center of Canal (core top)	1200020526	0 to 10 cm	GL045631	4.6	17000	2.2	49	73
	Center of Canal (core bottom)	1200020526	10 to 19 cm	GL045632	4.6	19000	2.2	54	88
	South side of canal	1200020540		GL045612	6.4	13000	2	38	56
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		GL045614	5.1	12000	1.5	35	50
	North side of canal (core top)	1200020527	0 to 7 cm	GL045633	5.1	9900	0.9 <T	33	46
	Center of Canal	1200020541		GL045613	1.5	4000	0.2 <=W	11	9
	South side of canal	1200020542		GL045615	2.5	6300	0.6 <T	18	23
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		GL045616	3.6	13000	1.1	40	94
	North side of canal (core top)	1200020528	0 to 10 cm	GL045635	3.6	16000	1.3	42	160**
	North side of canal (core bottom)	1200020528	20 to 31 cm	GL045636	3.6	17000	1.1	47	120**
	South side of canal	1200020543		GL045617	4.3	7500	0.8 <T	22	36
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	GL045639	4.2	8700	0.7 <T	26	71
7	Downstream end of Canal	1200020529		GL045619	3.8	10000	1.1	29	56
Lowest Effect Level							0.6	26	16
Severe Effect Level **							10	110	110

<W no measurable response

<T measurable trace amount

TABLE A1: Concentration of metals and particle size data for sediment collected from the Cornwall Canal, 2004.

All data represent surface samples (0-3 cm) unless noted as a core sample.

Values > LEL are in bold.

Values > SEL are designated **

Transect #	Station Description	Station	Core Length	Iron	Mercury	Total Hg	Methyl Hg	Manganese	Nickel
				UG/G DRY	UG/G DRY	ng/g (dry wt.) Flett	ng/g (dry wt.) Flett	UG/G DRY	UG/G DRY
1	West end of Canal								
	North side of canal	1200020533		9700	0.01 <=W			240	8.2
	Center of Canal	1200020534		11000	0.02 <T			200	12
	South side of canal	1200020523		9600	0.02 <T	27.3	0.7	200	10
	South side of canal (core top)	1200020523	0 to 6 cm	12000	0.01 <=W	192	0.4	320	11
2	Downstream of Lock (200m)								
	North side of canal	1200020524		20000	0.1			280	29
	North side of canal (core top)	1200020524	0 to 9 cm	12000	0.08			210	14
	Center of canal	1200020535		23000	0.1			320	34
	South side of canal	1200020536		25000	0.12			350	38
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		19000	0.15	134	0.6	310	27
	North side of canal (core top)	1200020525	0 to 12 cm	13000	0.08	129	0.3	230	16
	Center of Canal	1200020537		18000	0.08			400	24
	South side of canal	1200020538		16000	0.15			260	24
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		12000	0.13			160	18
	Center of canal	1200020526		11000	0.06	107	0.4	290	17
	Center of Canal (core top)	1200020526	0 to 10 cm	22000	0.25	418	0.2	340	34
	Center of Canal (core bottom)	1200020526	10 to 19 cm	25000	0.28	314	0.5	390	38
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		21000	0.18	271	0.8	280	27
	North side of canal (core top)	1200020527	0 to 7 cm	36000	0.21	1060	0.6	430	29
	Center of Canal	1200020541		7900	0.03 <T			140	7.5
	South side of canal	1200020542		11000	0.1			180	14
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		21000	0.46	666	0.7	230	43
	North side of canal (core top)	1200020528	0 to 10 cm	27000	0.71	1980	2.3	190	190**
	North side of canal (core bottom)	1200020528	20 to 31 cm	65000**	1.2	429	13	280	57
	South side of canal	1200020543		14000	0.15			230	35
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	18000	0.47	285	1.5	190	35
7	Downstream end of Canal	1200020529		17000	0.22	288	0.8	260	28
Lowest Effect Level				2%	0.2			460	16
Severe Effect Level **				4%	2			1100	75

<W no measurable response

<T measurable trace amount

TABLE A1: Concentration of metals and particle size data for sediment collected from the Cornwall Canal, 2004.

All data represent surface samples (0-3 cm) unless noted as a core sample.

Values > LEL are in bold.

Values > SEL are designated **

Transect #	Station Description	Station	Core Length	Lead	Zinc	LOI	TOC	Silt	Sand	Clay
				UG/G DRY	UG/G DRY	MG/G DRY	MG/G DRY	%	%	%
1	West end of Canal									
	North side of canal	1200020533		4 <T	32	14	16	13	75	4.3
	Center of Canal	1200020534		9 <T	45	23	23	25	66	7.3
	South side of canal	1200020523		2 <=W	35	17	18	17	72	5.4
	South side of canal (core top)	1200020523	0 to 6 cm	4 <T	28	8.1	12	30	57	9.9
2	Downstream of Lock (200m)									
	North side of canal	1200020524		44	130	83	65	67	12	21.3
	North side of canal (core top)	1200020524	0 to 9 cm	20	61	29	30	29	60	10.5
	Center of canal	1200020535		40	150	120	82	67	9	23.8
	South side of canal	1200020536		49	170	120	87	69	7	24.2
3	Upstream of Fertilizer Plant (200 m)									
	North side of canal	1200020525		84	190	110	91	52	33	14.6
	North side of canal (core top)	1200020525	0 to 12 cm	35	75	39	36	36	52	11.9
	Center of Canal	1200020537		45	120	180	160**	66	14	19.4
	South side of canal	1200020538		63	140	100	86	63	17	19.3
4	Downstream of "Domtar" outfall (5 m)									
	North side of canal	1200020539		40	110	420	470**	28	58	8.7
	Center of canal	1200020526		28	140	120	160**	65	7	28.3
	Center of Canal (core top)	1200020526	0 to 10 cm	87	230	140	130**	68	5	27
	Center of Canal (core bottom)	1200020526	10 to 19 cm	100	250	130	130**	70	2 <T	27.7
	South side of canal	1200020540		64	190	140	140**	66	8	26
5	Upstream of Domtar Door 16 (5 m)									
	North side of canal	1200020527		50	130	140	160**	56	28	16.1
	North side of canal (core top)	1200020527	0 to 7 cm	79	96	150	170**	47	40	13.6
	Center of Canal	1200020541		15	30	31	50	12	82	4.3
	South side of canal	1200020542		24	59	68	78	47	43	10.5
6	2nd part of Canal (west end of concrete platform)									
	North side of canal	1200020528		64	160	150	160**	53	33	14.2
	North side of canal (core top)	1200020528	0 to 10 cm	89	190	220	260**	56	25	19.2
	North side of canal (core bottom)	1200020528	20 to 31 cm	80	140	130	230**	70	12	17.7
	South side of canal	1200020543		28	76	79	84	28	59	9.8
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	39	94	81	120**	36	55	9.7
7	Downstream end of Canal	1200020529		43	110	86	70	37	52	11.1
Lowest Effect Level				31	120		1%			
Severe Effect Level **				250	820		10%			

<W no measurable response

<T measurable trace amount

TABLE A2: Concentration of organochlorinated pesticides, total PCBs and chlorinated benzenes in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station	Core length	Field Sample	Aladin	a-BHC	VQF	b-BHC	g-BHC	a-chterdane	g-chlordane
						NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY
1	West end of Canal										
	North side of canal	1200020533		GL045601	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of canal	1200020534		GL045603	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	South side of canal	1200020523		GL045602	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	South side of canal (core top)	1200020523	0 to 6 cm	GL045625	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
2	Downstream of Lock (200m)										
	North side of canal	1200020524		GL045605	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	North side of Canal (core top)	1200020524	0 to 9 cm	GL045627	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of canal	1200020535		GL045604	1 <=W	1 <=W	1 <=W	3 <T	2 <=W	2 <=W	2 <=W
	South side of canal	1200020536		GL045606	1 <=W	1 <=W	1 <=W	2 <T	2 <=W	2 <=W	2 <=W
3	Upstream of Fertilizer Plant (200 m)										
	North side of canal	1200020525		GL045608	1 <=W	3 <T	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	North side of canal (core top)	1200020525	0 to 12 cm	GL045629	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of Canal	1200020537		GL045607	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	2 <=W	2 <=W
	South side of canal	1200020538		GL045609	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
4	Downstream of "Domtar" outfall (5 m)										
	North side of canal	1200020539		GL045611	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of canal	1200020526		GL045610	1 <=W	2 <T	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of Canal (core top)	1200020526	0 to 10 cm	GL045631	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of Canal (core bottom)	1200020526	10 to 19 cm	GL045632	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
5	Upstream of Domtar Door 16 (5 m)										
	North side of canal	1200020527		GL045614	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	North side of canal (core top)	1200020527	0 to 7 cm	GL045633	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	Center of Canal	1200020541		GL045613	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	South side of canal	1200020542		GL045615	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
6	2nd part of Canal (west end of concrete platform)										
	North side of canal	1200020528		GL045616	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
	North side of canal (core top)	1200020528	0 to 10 cm	GL045635	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	3 <T
	North side of canal (core bottom)	1200020528	20 to 31 cm	GL045636	1 <=W	3 <T	1 <=W	1 <=W	1 <=W	2 <=W	3 <T
	South side of canal	1200020543		GL045617	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	GL045639	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W
7	Downstream end of Canal	1200020529		GL045619	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	2 <=W	2 <=W

<W no measurable response

<T measurable trace amount

TABLE A2: Concentration of organochlorinated pesticides, total PCBs and chlorinated benzenes in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station	Core length	Dieldrin	Methoxychlor	Endosulfan	Endosulfan II	Endrin	Endosulfan Sulfate	Heptachlor-epoxide	Heptachlor
				NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY
1	West end of Canal										
	North side of canal	1200020533		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	Center of canal	1200020534		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	South side of canal	1200020523		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	South side of canal (core top)	1200020523	0 to 6 cm	2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
2	Downstream of Lock (200m)										
	North side of canal	1200020524		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	2 <T	5 <T
	North side of Canal (core top)	1200020524	0 to 9 cm	2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	Center of canal	1200020535		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	4 <T	1 <=W
	South side of canal	1200020536		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	3 <T	4 <T
3	Upstream of Fertilizer Plant (200 m)										
	North side of canal	1200020525		2 <=W	15 <T	4 <T	9 <T	4 <=W	4 <=W	3 <T	1 <=W
	North side of canal (core top)	1200020525	0 to 12 cm	2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	Center of Canal	1200020537		3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	South side of canal	1200020538		2 <=W	16 <T	2 <=W	4 <=W	4 <=W	4 <=W	2 <T	1 <=W
4	Downstream of "Domtar" outfall (5 m)										
	North side of canal	1200020539		3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	2 <T	1 <=W
	Center of canal	1200020526		3 <T	5 <=W	2 <=W	5 <T	4 <=W	4 <=W	2 <T	1 <=W
	Center of Canal (core top)	1200020526	0 to 10 cm	4 <T	5 <=W	2 <=W	5 <T	4 <=W	4 <=W	1 <=W	1 <=W
	Center of Canal (core bottom)	1200020526	10 to 19 cm	3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	2 <T	1 <=W
5	Upstream of Domtar Door 16 (5 m)										
	North side of canal	1200020527		3 <T	5 <=W	2 <=W	5 <T	4 <=W	4 <=W	1 <=W	1 <=W
	North side of canal (core top)	1200020527	0 to 7 cm	2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	Center of Canal	1200020541		2 <=W	5 <=W	12 <T	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	South side of canal	1200020542		2 <=W	5 <=W	3 <T	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
6	2nd part of Canal (west end of concrete platform)										
	North side of canal	1200020528		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	North side of canal (core top)	1200020528	0 to 10 cm	3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	North side of canal (core bottom)	1200020528	20 to 31 cm	3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
	South side of canal	1200020543		2 <=W	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W
7	Downstream end of Canal	1200020529		3 <T	5 <=W	2 <=W	4 <=W	4 <=W	4 <=W	1 <=W	1 <=W

<W no measurable response

<T measurable trace amount

TABLE A2: Concentration of organochlorinated pesticides, total PCBs and chlorinated benzenes in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transsect #	Station Description	Station	Core length	Mirex	Oxychlordane	p,p'-DDT	Total PCB	PCB normalized for TGC	DDT and metabolites	p,p'-DDT	p,p'-DDE
				NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY	NG/G DRY
1	West end of Canal										
	North side of canal	1200020533		5 <=W	2 <=W	5 <=W	20 <=W	1250	2 <=W	5 <=W	2 <T
	Center of canal	1200020534		5 <=W	2 <=W	5 <=W	20 <=W	870	2 <=W	5 <=W	1 <=W
	South side of canal	1200020523		5 <=W	2 <=W	5 <=W	20 <=W	1111	2 <=W	5 <=W	1 <=W
	South side of canal (core top)	1200020523	0 to 6 cm	5 <=W	2 <=W	5 <=W	20 <=W	1667	2 <=W	5 <=W	1 <=W
2	Downstream of Lock (200m)										
	North side of canal	1200020524		5 <=W	2 <=W	5 <=W	51 P40	785	13 <T	5 <=W	5 <T
	North side of Canal (core top)	1200020524	0 to 9 cm	5 <=W	2 <=W	5 <=W	32 P40	1067	3 <T	5 <=W	3 <T
	Center of canal	1200020535		5 <=W	2 <=W	5 <=W	51 P40	622	3 <T	5 <=W	3 <T
	South side of canal	1200020536		5 <=W	2 <=W	5 <=W	49 P40	563	5 <T	5 <=W	5 <T
3	Upstream of Fertilizer Plant (200 m)										
	North side of canal	1200020525		5 <=W	2 <=W	5 <=W	61 P40	670	14 <T	9 <T	1 <=W
	North side of canal (core top)	1200020525	0 to 12 cm	5 <=W	2 <=W	5 <=W	80 P40	2222	3 <T	5 <=W	3 <T
	Center of Canal	1200020537		5 <=W	2 <=W	5 <=W	83 P40	519	3 <T	5 <=W	3 <T
	South side of canal	1200020538		5 <=W	2 <=W	5 <=W	68 P40	791	3 <T	5 <=W	3 <T
4	Downstream of "Domtar" outfall (5 m)										
	North side of canal	1200020539		5 <=W	2 <=W	5 <=W	210 P40	447	8 <T	5 <=W	8 <T
	Center of canal	1200020526		5 <=W	2 <=W	5 <=W	280 P40	1750	10 <T	5 <=W	10
	Center of Canal (core top)	1200020526	0 to 10 cm	5 <=W	2 <=W	5 <=W	200 P40	1538	12 <T	5 <=W	12
	Center of Canal (core bottom)	1200020526	10 to 19 cm	5 <=W	2 <=W	5 <=W	200 P40	1538	16 <T	6 <T	10
	South side of canal	1200020540		5 <=W	2 <=W	5 <=W	200 P40	1429	7 <T	5 <=W	7 <T
5	Upstream of Domtar Door 16 (5 m)										
	North side of canal	1200020527		5 <=W	2 <=W	5 <=W	160 P40	1000	6 <T	5 <=W	6 <T
	North side of canal (core top)	1200020527	0 to 7 cm	5 <=W	2 <=W	5 <=W	130 P40	765	6 <T	5 <=W	6 <T
	Center of Canal	1200020541		5 <=W	2 <=W	5 <=W	51 P40	1020	2 <=W	5 <=W	2 <T
	South side of canal	1200020542		5 <=W	2 <=W	5 <=W	42 P40	538	2 <=W	5 <=W	1 <=W
6	2nd part of Canal (west end of concrete platform)										
	North side of canal	1200020528		5 <=W	2 <=W	5 <=W	450 P40	2813	16 <T	5 <=W	16
	North side of canal (core top)	1200020528	0 to 10 cm	5 <=W	2 <=W	5 <=W	550 P40	2115	20	5 <=W	20
	North side of canal (core bottom)	1200020528	20 to 31 cm	5 <=W	2 <=W	5 <=W	490 P40	2130	23	8 <T	15
	South side of canal	1200020543		5 <=W	2 <=W	5 <=W	200 P40	2381	8 <T	5 <=W	8 <T
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	5 <=W	2 <=W	5 <=W	380 P40	3167	16 <T	5 <=W	16
7	Downstream end of Canal	1200020529		5 <=W	2 <=W	5 <=W	210 P40	3000	7 <T	5 <=W	7 <T

<W no measurable response

<T measurable trace amount

TABLE A2: Concentration of organochlorinated pesticides, total PCBs and chlorinated benzenes in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station	Core length	p,p'-DDT NG/G DRY	Toxaphene NG/G DRY	Hexachloro- Dutadiene NG/G DRY	1,2,3 Tri- chlorobenzene NG/G DRY	1,2,3,4 Tetra- chlorobenzene NG/G DRY	1,3,5 Tetra- chlorobenzene NG/G DRY	1,2,4 Tri- chlorobenzene NG/G DRY	1,2,4,5 Tetra- chlorobenzene NG/G DRY
1	West end of Canal										
	North side of canal	1200020533		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	Center of canal	1200020534		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	South side of canal	1200020523		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	South side of canal (core top)	1200020523	0 to 6 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
2	Downstream of Lock (200m)										
	North side of canal	1200020524		8 <T	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	North side of Canal (core top)	1200020524	0 to 9 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	Center of canal	1200020535		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	South side of canal	1200020536		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
3	Upstream of Fertilizer Plant (200 m)										
	North side of canal	1200020525		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	North side of canal (core top)	1200020525	0 to 12 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	Center of Canal	1200020537		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	South side of canal	1200020538		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
4	Downstream of "Domtar" outfall (5 m)										
	North side of canal	1200020539		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	Center of canal	1200020526		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	Center of Canal (core top)	1200020526	0 to 10 cm	5 <=W	50 <=W	1 <=W	10 <T	1 <=W	1 <=W	9 <T	4 <T
	Center of Canal (core bottom)	1200020526	10 to 19 cm	5 <=W	50 <=W	1 <=W	2 <=W	2 <T	1 <=W	11 <T	1 <=W
	South side of canal	1200020540		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
5	Upstream of Domtar Door 16 (5 m)										
	North side of canal	1200020527		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	North side of canal (core top)	1200020527	0 to 7 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	12 <T	1 <=W
	Center of Canal	1200020541		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	South side of canal	1200020542		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
6	2nd part of Canal (west end of concrete platform)										
	North side of canal	1200020528		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
	North side of canal (core top)	1200020528	0 to 10 cm	5 <=W	50 <=W	1 <=W	2 <=W	5 <T	1 <=W	20	1 <=W
	North side of canal (core bottom)	1200020528	20 to 31 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	16 <T	1 <=W
	South side of canal	1200020543		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	11 <T	1 <=W
7	Downstream end of Canal	1200020529		5 <=W	50 <=W	1 <=W	2 <=W	1 <=W	1 <=W	2 <=W	1 <=W

<W no measurable response

<T measurable trace amount

TABLE A2: Concentration of organochlorinated pesticides, total PCBs and chlorinated benzenes in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station	Core length	1,3,5 Tri- chlorobenzene NG/G DRY	Hexachloro- benzene NG/G DRY	Hexachloro- ethane NG/G DRY	Octachloro- styrene NG/G DRY	Pentachloro- benzene NG/G DRY	2,3,5 Trichloro- toluene NG/G DRY	2,4,5 Trichloro- toluene NG/G DRY	2,6A Trichloro- toluene NG/G DRY
1	West end of Canal										
	North side of canal	1200020533		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	Center of canal	1200020534		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	South side of canal	1200020523		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	South side of canal (core top)	1200020523	0 to 6 cm	2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
2	Downstream of Lock (200m)										
	North side of canal	1200020524		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	North side of Canal (core top)	1200020524	0 to 9 cm	2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	Center of canal	1200020535		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	South side of canal	1200020536		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
3	Upstream of Fertilizer Plant (200 m)										
	North side of canal	1200020525		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	North side of canal (core top)	1200020525	0 to 12 cm	2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	Center of Canal	1200020537		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	South side of canal	1200020538		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
4	Downstream of "Domtar" outfall (5 m)										
	North side of canal	1200020539		2 <=W	3 <T	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
	Center of canal	1200020526		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	Center of Canal (core top)	1200020526	0 to 10 cm	2 <=W	1 <=W	1 <=W	1 <=W	3 <T	1 <=W	1 <=W	1 <=W
	Center of Canal (core bottom)	1200020526	10 to 19 cm	43	1 <=W	1 <=W	1 <=W	6 <T	1 <=W	1 <=W	1 <=W
	South side of canal	1200020540		4 <T	1 <=W	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
5	Upstream of Domtar Door 16 (5 m)										
	North side of canal	1200020527		2 <=W	1 <=W	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
	North side of canal (core top)	1200020527	0 to 7 cm	2 <=W	1 <=W	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
	Center of Canal	1200020541		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	South side of canal	1200020542		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
6	2nd part of Canal (west end of concrete platform)										
	North side of canal	1200020528		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
	North side of canal (core top)	1200020528	0 to 10 cm	2 <=W	1 <=W	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
	North side of canal (core bottom)	1200020528	20 to 31 cm	2 <=W	1 <=W	1 <=W	1 <=W	2 <T	1 <=W	1 <=W	1 <=W
	South side of canal	1200020543		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W
7	Downstream end of Canal	1200020529		2 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W	1 <=W

<W no measurable response

<T measurable trace amount

TABLE A3: Concentration of polycyclic aromatic hydrocarbons in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station number	Core Length	Field Sample number	Acenaphthene		Acenaphthylene		Anthracene		Benzo(a)anthracene	
					ng/g (dry wt.)	RMK	ng/g (dry wt.)	RMK	ng/g (dry wt.)	RMK	ng/g (dry wt.)	RMK
1	West end of Canal											
	North side of canal	1200020533		GL045601	<=W		<=W		3	<T	11	<T
	Center of canal	1200020534		GL045603	<=W		<=W		3.2	<T	9	<T
	South side of canal	1200020523		GL045602	<=W		<=W		2.7	<T	9	<T
	South side of canal (core top)	1200020523	0 to 6 cm	GL045625	<=W		<=W		<=W		3	<T
2	Downstream of Lock (200m)											
	Center of canal	1200020535		GL045604	9	<T	17	<T	23		93	
	North side of canal	1200020524		GL045605	5	<T	19	<T	20		79	
	North side of canal (core top)	1200020524	0 to 9 cm	GL045627	15	<T	5	<T	24		48	
	South side of canal	1200020536		GL045606	8	<T	15	<T	24		100	
3	Upstream of Fertilizer Plant (200 m)											
	North side of canal	1200020525		GL045608	660		790		2200		6200	
	North side of canal (core top)	1200020525	0 to 12 cm	GL045629	15	<T	11	<T	28		95	
	Center of Canal	1200020537		GL045607	56		29		120		700	
	South side of canal	1200020538		GL045609	140		21		300		860	
4	Downstream of "Domtar" outfall (5 m)											
	North side of canal	1200020539		GL045611	790		120		2000		2500	
	Center of canal	1200020526		GL045610	370		140		900		3000	
	Center of Canal (core top)	1200020526	0 to 10 cm	GL045631	110		44		250		810	
	Center of Canal (core bottom)	1200020526	10 to 19 cm	GL045632	86		91		180		460	
	South side of canal	1200020540		GL045612	230		160		560		1800	
5	Upstream of Domtar Door 16 (5 m)											
	North side of canal	1200020527		GL045614	110		130		240		810	
	North side of canal (core top)	1200020527	0 to 7 cm	GL045633	89		59		130		340	
	Center of Canal	1200020541		GL045613	67		11	<T	35		69	
	South side of canal	1200020542		GL045615	27		24		52		170	
6	2nd part of Canal (west end of concrete platform)											
	North side of canal	1200020528		GL045616	110		56		250		660	
	North side of canal (core top)	1200020528	0 to 10 cm	GL045635	220		150		230		480	
	North side of canal (core bottom)	1200020528	20 to 31 cm	GL045636	150		73		190		520	
	South side of canal	1200020543		GL045617	58		60		150		300	
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	GL045639	340		160		370		820	
7	Downstream end of Canal	1200020529		GL045619	190		37		210		390	

<W no measurable response

<T measurable trace amount

TABLE A3: Concentration of polycyclic aromatic hydrocarbons in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station number	Core Length	Benzo(a) pyrene	Benzo(b) fluoranthene	Benzo(e) pyrene	Benzo(k) fluoranthene	Chrysene	Dibenzo(ah) anthracene
				ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK
1	West end of Canal								
	North side of canal	1200020533		9 <T	18 <T	10 <T	7 <T	15 <T	3 <T
	Center of canal	1200020534		9 <T	23	12 <T	8 <T	16 <T	5 <T
	South side of canal	1200020523		7.4 <T	19 <T	9.5 <T	6.7 <T	13 <T	4.2 <T
	South side of canal (core top)	1200020523	0 to 6 cm	<=W	6 <T	3 <T	<=W	6 <T	<=W
2	Downstream of Lock (200m)								
	Center of canal	1200020535		120	230	140	91	230	27
	North side of canal	1200020524		94	200	110	75	150	25
	North side of canal (core top)	1200020524	0 to 9 cm	44	85	50	33	76	9 <T
	South side of canal	1200020536		140	280	160	110	220	26
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		6400	13000	6600	5000	15000	840
	North side of canal (core top)	1200020525	0 to 12 cm	100	190	110	77	170	21
	Center of Canal	1200020537		1000	1700	960	730	1300	170
	South side of canal	1200020538		1000	1500	870	640	1200	160
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		2400	3100	1700	1400	3400	350
	Center of canal	1200020526		3200	4700	2500	2100	4500	540
	Center of Canal (core top)	1200020526	0 to 10 cm	860	1500	860	600	1400	150
	Center of Canal (core bottom)	1200020526	10 to 19 cm	450	850	540	330	960	89
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		810	1200	760	540	1200	160
	North side of canal (core top)	1200020527	0 to 7 cm	320	540	320	220	600	56
	Center of Canal	1200020541		54	98	73	35	140	11 <T
	South side of canal	1200020542		180	290	170	120	280	29
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		740	1100	810	480	1100	140
	North side of canal (core top)	1200020528	0 to 10 cm	470	650	700	250	860	110
	North side of canal (core bottom)	1200020528	20 to 31 cm	530	750	730	340	940	170
	South side of canal	1200020543		320	490	320	200	510	58
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	790	1100	700	460	1300	130
7	Downstream end of Canal	1200020529		400	630	370	270	600	69

<W no measurable response

<T measurable trace amount

TABLE A3: Concentration of polycyclic aromatic hydrocarbons in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station number	Core Length	Fluoranthene	Fluorene	Benzo(g,h,i) perylene	Indeno(1,2,3-cd) pyrene	Naphthalene	Perylene
				ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK	ng/g (dry wt.) RMK
1	West end of Canal								
	North side of canal	1200020533		25	4 <T	9 <T	8 <T	10 <T	15 <T
	Center of canal	1200020534		24	3.8 <T	12 <T	12 <T	16 <T	35
	South side of canal	1200020523		24	5.3 <T	11 <T	8.4 <T	12 <T	20
	South side of canal (core top)	1200020523	0 to 6 cm	9 <T	7 <T	3 <T	3 <T	8 <T	13 <T
2	Downstream of Lock (200m)								
	Center of canal	1200020535		250	20	130	140	53	200
	North side of canal	1200020524		200	19 <T	93	110	68	210
	North side of canal (core top)	1200020524	0 to 9 cm	150	29	39	50	67	94
	South side of canal	1200020536		300	22	150	160	52	220
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		30000	1800	4300	4400	1400	1100
	North side of canal (core top)	1200020525	0 to 12 cm	260	36	90	110	190	100
	Center of Canal	1200020537		2200	100	960	990	430	350
	South side of canal	1200020538		2400	160	810	910	170	370
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		6600	1200	1500	1600	6900	660
	Center of canal	1200020526		6900	570	2700	3000	1800	930
	Center of Canal (core top)	1200020526	0 to 10 cm	1900	300	710	910	2000	370
	Center of Canal (core bottom)	1200020526	10 to 19 cm	1100	350	370	460	3400	260
	South side of canal	1200020540		4100	450	1600	1700	3400	620
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		1800	280	610	720	3600	300
	North side of canal (core top)	1200020527	0 to 7 cm	810	250	230	290	2300	120
	Center of Canal	1200020541		190	100	45	48	190	28
	South side of canal	1200020542		350	82	120	160	470	90
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		1500	230	700	790	780	260
	North side of canal (core top)	1200020528	0 to 10 cm	1100	510	340	410	1500	210
	North side of canal (core bottom)	1200020528	20 to 31 cm	1000	330	470	650	1800	210
	South side of canal	1200020543		790	140	250	320	490	99
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	2200	490	480	630	860	270
7	Downstream end of Canal	1200020529		1100	320	300	380	860	130

<W no measurable response

<T measurable trace amount

TABLE A3: Concentration of polycyclic aromatic hydrocarbons in sediment collected from the Cornwall Canal, 2004.
All data represent surface samples (0-3 cm) unless noted as a core sample.

Transect #	Station Description	Station number	Core Length	Phenanthrene	Pyrene	Total PAHs	PAH normalized for TOC	SEL
				ng/g (dry wt.)	ng/g (dry wt.)	ng/g (dry wt.)		ug/g org carbon
				RMK	RMK			
1	West end of Canal							
	North side of canal	1200020533		18 <T	18 <T	158	9875	160
	Center of canal	1200020534		20	17 <T	178	7739	230
	South side of canal	1200020523		21	16 <T	160	8872	180
	South side of canal (core top)	1200020523	0 to 6 cm	8 <T	7 <T	60	5000	120
2	Downstream of Lock (200m)							
	Center of canal	1200020535		120	190	1743	21256	820
	North side of canal	1200020524		100	160	1417	21800	650
	North side of canal (core top)	1200020524	0 to 9 cm	100	120	894	29800	300
	South side of canal	1200020536		130	240	1977	22724	870
3	Upstream of Fertilizer Plant (200 m)							
	North side of canal	1200020525		25000	27000	143990	1582308	910
	North side of canal (core top)	1200020525	0 to 12 cm	160	230	1783	49528	360
	Center of Canal	1200020537		790	1800	13075	81719	1600
	South side of canal	1200020538		1300	1900	13471	156640	860
4	Downstream of "Domtar" outfall (5 m)							
	North side of canal	1200020539		6800	5400	46060	98000	4700
	Center of canal	1200020526		4200	5900	44520	278250	1000
	Center of Canal (core top)	1200020526	0 to 10 cm	1600	1700	14844	114185	1000
	Center of Canal (core bottom)	1200020526	10 to 19 cm	1600	1000	11776	90585	1000
	South side of canal	1200020540		2800	3600	29550	211071	1000
5	Upstream of Domtar Door 16 (5 m)							
	North side of canal	1200020527		1500	1500	15210	95063	1000
	North side of canal (core top)	1200020527	0 to 7 cm	1000	740	7974	46906	1000
	Center of Canal	1200020541		300	170	1563	31260	500
	South side of canal	1200020542		340	320	3014	38641	780
6	2nd part of Canal (west end of concrete platform)							
	North side of canal	1200020528		1300	1300	11236	70225	1000
	North side of canal (core top)	1200020528	0 to 10 cm	1600	980	9860	37923	1000
	North side of canal (core bottom)	1200020528	20 to 31 cm	1400	990	10303	44796	1000
	South side of canal	1200020543		710	730	5576	66381	840
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	2300	1900	14330	119417	1000
7	Downstream end of Canal	1200020529		1100	830	7686	109800	700

<W no measurable response

<T measurable trace amount

APPENDIX B: Sediment metal concentrations normalized for particle size differences. All data adjusted to reflect a particle size of 67% silt/clay which is the median for the survey area. Cornwall Canal, 2004

Transect #	Station Description	Station	Core Length	Field Sample	% Silt+Clay for each sample	Aluminum (corrected)	Cadmium (corrected)	Chromium (corrected)	Copper (corrected)
1	West end of Canal								
	North side of canal	1200020533		GL045601	17.3	18977	2	46	27
	Center of Canal	1200020534		GL045603	32.3	11616	2	33	23
	South side of canal	1200020523		GL045602	22.4	14357	1	39	27
	South side of canal (core top)	1200020523	0 to 6 cm	GL045625	39.9	9739	1	24	15
2	Downstream of Lock (200m)								
	North side of canal	1200020535		GL045604	90.8	12544	1	37	41
	North side of canal (core top)	1200020524		GL045605	88.3	10623	1	32	42
	Center of canal	1200020524	0 to 9 cm	GL045627	39.5	13061	2	37	36
	South side of canal	1200020536		GL045606	93.2	12940	2	38	44
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		GL045608	66.6	13078	2	39	62
	North side of canal (core top)	1200020525	0 to 12 cm	GL045629	47.9	11610	1	34	48
	Center of Canal	1200020537		GL045607	85.4	8630	1	24	31
	South side of canal	1200020538		GL045609	82.3	8955	1	27	43
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		GL045611	36.7	12597	2	31	64
	Center of canal	1200020526		GL045610	93.3	6104	1	16	23
	Center of Canal (core top)	1200020526	0 to 10 cm	GL045631	95	11989	2	35	51
	Center of Canal (core bottom)	1200020526	10 to 19 cm	GL045632	97.7	13030	2	37	60
	South side of canal	1200020540		GL045612	92	9467	1	28	41
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		GL045614	72.1	11151	1	33	46
	North side of canal (core top)	1200020527	0 to 7 cm	GL045633	60.6	10946	1	36	51
	Center of Canal	1200020541		GL045613	16.3	16442	1	45	37
	South side of canal	1200020542		GL045615	57.5	7341	1	21	27
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		GL045616	67.2	12961	1	40	94
	North side of canal (core top)	1200020528	0 to 10 cm	GL045635	75.2	14255	1	37	143
	North side of canal (core bottom)	1200020528	20 to 31 cm	GL045636	87.7	12987	1	36	92
	South side of canal	1200020543		GL045617	37.8	13294	1	39	64
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	GL045639	45.7	12755	1	38	104
7	Downstream end of Canal	1200020529		GL045619	48.1	13929	2	40	78

APPENDIX B: Sediment metal concentrations normalized for particle size differences. All data adjusted to reflect a particle size of 67% silt/clay which is the median for the survey area. Cornwall Canal, 2004

Transect #	Station Description	Station	Core Length	Iron (corrected)	Mercury (corrected)	Manganese (corrected)	Nickel (corrected)	Lead (corrected)	Zinc (corrected)
1	West end of Canal								
	North side of canal	1200020533		37566	0.04	929	32	15	124
	Center of Canal	1200020534		22817	0.04	415	25	19	93
	South side of canal	1200020523		28714	0.06	598	30	6	105
	South side of canal (core top)	1200020523	0 to 6 cm	20150	0.02	537	18	7	47
2	Downstream of Lock (200m)								
	North side of canal	1200020535		16971	0.07	236	25	30	111
	North side of canal (core top)	1200020524		15176	0.08	212	22	33	99
	Center of canal	1200020524	0 to 9 cm	20354	0.14	356	24	34	103
	South side of canal	1200020536		17972	0.09	252	27	35	122
3	Upstream of Fertilizer Plant (200 m)								
	North side of canal	1200020525		19114	0.15	312	27	85	191
	North side of canal (core top)	1200020525	0 to 12 cm	18184	0.11	322	22	49	105
	Center of Canal	1200020537		14122	0.06	314	19	35	94
	South side of canal	1200020538		13026	0.12	212	20	51	114
4	Downstream of "Domtar" outfall (5 m)								
	North side of canal	1200020539		21907	0.24	292	33	73	201
	Center of canal	1200020526		7899	0.04	208	12	20	101
	Center of Canal (core top)	1200020526	0 to 10 cm	15516	0.18	240	24	61	162
	Center of Canal (core bottom)	1200020526	10 to 19 cm	17144	0.19	267	26	69	171
	South side of canal	1200020540		13837	0.12	233	20	47	138
5	Upstream of Domtar Door 16 (5 m)								
	North side of canal	1200020527		19515	0.17	260	25	46	121
	North side of canal (core top)	1200020527	0 to 7 cm	39802	0.23	475	32	87	106
	Center of Canal	1200020541		32472	0.12	575	31	62	123
	South side of canal	1200020542		12817	0.12	210	16	28	69
6	2nd part of Canal (west end of concrete platform)								
	North side of canal	1200020528		20938	0.46	229	43	64	160
	North side of canal (core top)	1200020528	0 to 10 cm	24056	0.63	169	169	79	169
	North side of canal (core bottom)	1200020528	20 to 31 cm	49658	0.92	214	44	61	107
	South side of canal	1200020543		24815	0.27	408	62	50	135
6A	Under Bridge to USA (core top)	1200020530	0 to 7 cm	26389	0.69	279	51	57	138
7	Downstream end of Canal	1200020529		23680	0.31	362	39	60	153

APPENDIX C: Median metal, total phosphorus and TOC concentrations ($\mu\text{g/g}$ dry weight) in sediment samples (top 10 cm core sample and 3 cm surface samples) collected from the St. Lawrence River, 1997.

Parameters	Median, Minimum and Maximum Concentrations of Contaminants in Sediment											
	Cornwall waterfront (downstream of industrial discharges)						North Shore of Cornwall Island					
	Surface (3 cm)	min	max	Core (10 cm)	min	max	Surface (3 cm)	min	max	Core (10 cm)	min	max
Aluminum	14800	10300	23400	16800	9630	31200	23700	21700	27500	28600	24300	33300
Cadmium	0.758	0.359	1.120	0.888	0.473	1.450	0.990	0.916	1.100	1.020	0.901	1.210
Chromium	32.0	25.1	49.1	37.5	23.8	58.8	42.7	39.7	48.7	50.6	43.8	59.1
Copper	37.6	19.3	57.6	42.5	16.9	60.9	33.7	30.6	41.5	38.9	31.8	46.3
Iron	15900	13100	22200	17300	12700	26600	22950	20800	26200	26500	23500	30000
Mercury	1.63	0.70	14.70	3.06	0.44	19.50	0.13	0.12	0.15	0.13	0.08	0.15
Manganese	293	222	357	292	201	439	479	386	665	489	435	592
Nickel	24.9	14.5	30.2	24.0	13.8	34.1	33.0	28.4	38.4	30.8	28.4	35.4
Total Phosphorus	852	653	1020	745	457	1150	971	698	1110	1090	996	1180
Lead	33.7	19.7	156.0	44.0	25.2	136.0	26.8	26.3	29.5	35.2	27.2	39.3
Zinc	133	69	673	186	102	759	118	110	136	136	117	156
TOC (%)	2.370	1.753	3.491	2.516	1.681	4.037	2.953	2.528	3.229	2.532	2.030	3.130

(Richman, 1997)

[illegible]



96936000009284